




PG2HTA - PG3HTA - PG4HTA

Instructions for use


1- Longitudinal cut

- Position the PG HTA pliers as shown to the desired length.
- Tighten the pliers until the cutting wheel penetrates onto stop rollers.
- Pull the pliers along the length to be stripped in the direction shown by the arrow.




2- Circular cut

- Position the PG HTA pliers at the end of the longitudinal cut.
- Close the pliers on the cables pressing slightly to ensure penetration of the cutting wheels.
- Rotate the pliers back and forth by a third of revolution



3- Sheath removal

- Use the two end blades to separate the sheath.



- ☞ The tools must be used when the cable is out of tension by skilled workers who are competent in cable preparation and know about electrical phenomena.
- ☞ Wearing anti-cut gloves is obligatory.
- ☞ Clean the tools after each utilization.

ALROC S.A.S - ZI de la Fonderie - 72160 TUFFE - FRANCE - Phone : 33.(0)2.43.71.11.80 - Fax : 33.(0)2.43.71.16.51
Internet : www.alroc.fr - E.mail : commercial@alroc.fr - info@alroc.fr

S.A.S au capital de 800000€ - 341 050 987 RCS LE MANS - SIRET 341 050 987 00013 - APE 2453Z - TVA/FR 77 341 050 987